UNCLASSIFIED
AD NUMBER
AD832195
LIMITATION CHANGES
TO: Approved for public release; distribution is unlimited.
FROM: Distribution authorized to U.S. Gov't. agencies and their contractors; Critical Technology; MAR 1968. Other requests shall be referred to Air Force Technical Application Center. Washington.

Force Technical Application Center, Washington, DC 20333. This document contains exportcontrolled technical data.

AUTHORITY


usaf ltr, 25 jan 1972 xxx

TECHNICAL REPORT NO. 68-17

OPERATION OF
THE TONTO FOREST SEISMOLOGICAL OBSERVATORY
Quartely Report No.1, Project VT/8702
1 January through 31 March 1968

SPATEMENT #2 UNCLASSIVI

transmittal to foreign governments or foreign nationals and transmittal to foreign governments or foreign nationals and transmittal to foreign governments of foreign nationals and transmittal to foreign governments or foreign nationals and transmittal to foreign nationals and transmittal to foreign nationals and transmittal na





TECHNICAL REPORT NO. 68-17

OPERATION OF THE
TONTO FOREST SEISMOLOGICAL OBSERVATORY
Quarterly Report No. 1, Project VT/8702
1 January through 31 March 1968

Sponsored by

Advanced Research Projects Agency Nuclear Test Detection Office ARPA Order No. 624

> GEOTECH A Teledyne Company 3401 Shiloh Road Garland, Texas

<u>IDENTIFICATION</u>

AFTAC Project No:

Project Title:

ARPA Order No:

ARPA Program Code No:

Name of Contractor:

Date of Contract:

Amount of Contract:

Contract Number:

Contract I .piration Date:

Program Manager:

VELA T/8702

Operation of TFSO

624

8F10

Teledyne Industries Incorporated

Geotech Division

Garland, Texas

1 January 1968

Not negotiated

AF 33657-68-C-0766

31 December 1968

B. B. Leichliter, BR1-2561

CONTENTS

			Page
ΑE	STRA	CT	
1.	INT	RODUCTION	
		Authority	1
		History	1
		,	1
2.	OPE	CRATION OF TFSO	1
	2.1	General	1
	2.2	Standard seismograph operating parameters	1
	2.3	Data channel assignments	4
	2.4	Completion and shipment of data	4
	2.5	Quality control	4
		2.5.1 Quality control of 16-mm film seismograms	4
		2.5.2 Quality control of magnetic-tape seismograms	6
	2.6	Small Business Administration visit	7
		Security Inspection	7
	2.8	Emergency power generator	7
3.	EVA	LUATE DATA AND DETERMINE OPTIMUM	7
		RATIONAL CHARACTERISTICS	•
	3.1	Short-period array systems modifications	7
	3.2	Maintain TFSO facilities	8
4.	ANA	LYZE DATA	8
	4.1		8
	4.2	Daily analysis for multistation earthquake bulletin	10
	4.3	Routine noise survey	10
5.	PRO TO C	VIDE OBSERVATORY FACILITIES AND ASSISTANCE OTHER ORGANIZATIONS	14
	5.1	Astrodata data acquisition system	14
	5.2	Telemetry to Massachusetts Institute of Technology	14
	5.3	Astrogeological Department of the U.S. Geological Survey	14
	5.4	Visitors	15
		5.4.1 Visits by school groups	15
		5.4.2 Teledyne visitors	15
		5.4.3 Visits by Project Managers	15
		5.4.4 Texas Instruments visit	15

CONTENTS, Continued

			<u> Page</u>
6.	RESI	EARCH PROGRAMS	15
	6.1	Design and install a long-period array	15
		6.1.1 Land permitting	15
		6.1.2 Array installation	16
		6.1.3 Long-period site survey	16
	6.2	Evaluation of a high-frequency seismograph	16
	6.3	Multichannel filter processor	16

ILLUSTRATIONS

Figure		Page
1	Location of TFSO	2
2	Normalized response characteristics of standard seismographs at TFSO	5
3	Block diagram of the power system for the short- period seismographs showing modifications made to system to reduce noise and spiking due to leakage	9
4	Distribution of Coast and Geodetic Survey located epicenters in the northern hemisphere for August, September, and October 1967	12
5	Distribution of Coast and Geodetic Survey located epicenters in the southern hemisphere for August, September, and October 1967	13
6	TFSO short-period seismogram showing the beamformed MCF outputs responding to a teleseismic Parrival from the southeast - epicenter unknown (X10 enlargement of 16-millimeter film)	19
7	TFSO short-period seismogram showing the beam- formed MCF outputs responding to a teleseismic Parrival from the northwest - epicenter unknown (X10 enlargement of 16-millimeter film)	20
8	TFSO short-period seismogram showing the beam- formed MCF outputs responding to a teleseismic P arrival from the west-southwest - epicenter unknown (X10 enlargement of 16-millimeter film)	21

TABLES

Table		Page
1	Operating parameters and tolerances of standard seismographs at TFSO	3
2	Events reported to the C&GS by TFSO during January, February, and March 1968	10
3	Percentage of hypocenters reported in the C&GS "Earthquake Data Report" for which TFSO data were used	11
4	Beams being formed by the multichannel filter using TFSO short-period array seismographs	18

ABSTRACT

This is a report of the work accomplished on Project VT/8702 from 1 January through 31 March 1968. Project VT/8702 includes the operation, evaluation, and improvement of the Tonto Forest Seismological Observatory (TFSO) located near Payson, Arizona. It also includes special research and test functions carried out at TFSO and research and development tasks performed by the Garland, Texas, staff using TFSO data.

BLANK PAGE

OPERATION OF THE TONTO FOREST SEISMOLOGICAL OBSERVATORY

1. INTRODUCTION

1.1 AUTHORITY

The research described in this report was supported by the Advanced Research Projects Agency, Nuclear Test Detection Office and was monitored by the Air Force Technical Applications Center (AFTAC) under Letter Contract AF 33657-68-C-0766. The effective date of the contract is 1 January 1968; the statement of work for Project VT/8702 is included as the appendix to this report.

1.2 HISTORY

The Tonto Forest Seismological Observatory (TFSO) was constructed by the United States Corps of Engineers in 1963. TFSO was designed to record seismic events and to be used as a laboratory for testing, comparing, and evaluating advanced seismograph equipment and seismometric recording techniques. The instrumentation was assembled, installed, and operated until 30 April 1965, by the Earth Sciences Division of Teledyne Industries, under Contract AF 33(657)-7747. On 1 May 1965, Geotech assumed the responsibility for operating TFSO. The location of TFSO is shown in figure 1.

2. OPERATION OF TFSO

2.1 GENERAL

Data are recorded at TFSO on a 24-hour-a-day basis. The observatory is manned continuously. A full complement of personnel is on duty 8 hours a day, 5 days a week; at other times, a reduced operating crew is on duty.

2.2 STANDARD SEISMOGRAPH OPERATING PARAMETERS

The operating parameters and tolerances for the TFSO standard seismographs are shown in table 1. Frequency response tests are made routinely, and




Figure 1. Location of TFSO

Operating parameters and tolerances of standard seismographs at TFSO Table 1.

		Seismograph		Oper	Operating parameters and tolerances	ers and toler	ances	ĺ	Filter settings	gs
System	Comp	Туре	Model	E S	λs	T	20	62	Bandpass at 3 dB cutoff (sec)	Cutoff rate at SP side (dB/oct)
SPa	Z	Johnson-Matheson	6480	1.25 ±2%	0.54 ±5%	;	;	0.0000	0.3 - 10	9
SPS	2 1	Johnson-Matheson	6480	1.25 ±2%	0.54 ±5%	0.33 ±5%	0.65 ±5%	0.0117	0.1 - 100	12
SP	Z	Benioff	1051	1.6 ±2%	1.0 ±5%	0.2 ±5%	1.0 ±5%	0.0104	0.1 - 100	12
SP	Ή	Benioff	1101	1.0 ±2%	1.0 ±5%	0.2 ±5%	1.0 ±5%	0.0104	0.1 - 100	12
SP	Z	UA Benioff	1051	1.0 ±2%	1.0 ±5%	0.75		0.0245	-	!
SP	H	UA Benioff	1101	1.0 ±2%	1.0 ±5%	0.75		0.0245	-	;
SP	H	Wood-Anderson	TS 220	0.8	0.78	;	:	;	1	:
IB	Z	Melton	10012	2.25 ±5%	0.65 ±5%	0.64 ±5%	1.2 ±5%	0.0006	0.05 - 100	18
IB	н	Lehner-Griffith	SH-216	2.25 ± 5%	0.65 ±5%	0.64 ±5%	1.2 ±5%	0.0004	0.05 - 100	18
LP	Z	Ceotech	7505A	20.0 ±5%	0.77	-	-	00.00	80 - 300	9
LP	H	Geotech	8700C	20.0 ±5%	0.77	}	1	0.00	80 - 300	9
				;						

KEY		
SP Short period IB Intermediate band LP Long period UA Unamplified (i.e., earth powered)	Ts Sei Tg Gal λs Sei λs Gal	Ts Seismometer free period (sec) Tg Galvanometer free period (sec) As Seismometer damping constant As Galvanometer damping constant
	6 ² Cot	Coupling coefficient
^a 37-element hexagonal array ^b Linear array and 3 comp	exagonal	array mp

parameters are checked and reset to maintain the specified tolerances.

Normalized response characteristics of TFSO standard seismographs are shown in figure 2. In addition to these standard seismographs, two filtered summation seismographs are recorded. One Σ TF seismograph is filtered by a UED filter with a high-cut frequency of 1.75 cps and a slope of 12 dB per octave. This seismograph is recorded on 16-millimeter film data trunks 1 and 7 and on magnetic-tape data trunks 2 and 5. The second Σ TFK seismograph utilizes a Krohn-Hite filter; the high-cut frequency is set at 2.0 cps with a slope of 24 dB per octave, and the low-cut frequency is set at 1.0 cps with a slope of 24 dB per octave. This filtered seismograph is recorded on 16-millimeter film data trunk 1.

2.3 DATA CHANNEL ASSIGNMENTS

Each data format recorded at TFSO is assigned a data group number. When a data format is changed, a new data group number is assigned. Several data format change notices reporting changes in channel assignments were submitted to the Project Officer and to frequent users of TFSO data during this reporting period.

2.4 COMPLETION AND SHIPMENT OF DATA

The magnetic-tape seismograms are shipped from TFSO each week. Six magnetic-tape recorders are used to record data for the AFTAC VELA Seismological Center (VSC).

Film seismograms from 10 Develocorders are routinely shipped to data users. The film and magnetic-tape operation logs and calibration logs are copied and shipped with the seismograms. Copies of selected film-seismogram data are sent to the Geotech Program Manager regularly and to other data users on special request. The shipments of 16-millimeter film seismograms routinely sent to the Seismic Data Laboratory (SDL) repository are complete through January 1968, except for selected seismograms being held for use in conjunction with special investigations or instrument tests that are in progress.

2.5 QUALITY CONTROL

2.5.1 Quality Control of 16-Millimeter Film Seismograms

Quality control checks of randomly selected 16-millimeter film seismograms from data trunks 1, 2, and 8, and the associated operation logs are made in




Figure 2. Normalized response characteristics of standard seismographs at TFSO

Garland. Items that are routinely checked by the Quality Control Analyst include:

- a. Film boxes neatness and completeness of box markings;
- b. Develocorder logs completeness, accuracy and legibility of logs;
- c. Film:
- (1) Quality of the overall appearance of the record (for example, trace spacing and tract intensity);
 - (2) Quality of film processing;
- d. Analysis completeness, legibility, and accuracy of the analysis sheets.

Results of these evaluations are sent to the observatory for their review and comment.

2.5.2 Quality Control of Magnetic-Tape Seismograms

Routine quality control checks of randomly selected magnetic-tape seismograms were made in Garland and at TFSO to assure that recordings met specified standards. The following are among the items that were checked by the Quality Control Group:

- a. Tape and box labeling;
- b. Accuracy, completeness, and neatness of logs;
- c. Adequate documentation of logs by voice comments on tape where applicable;
 - d. Seismograph polarity;
 - e. Level of calibration signals;
 - f. Relative phase shift between array seismographs;
 - g. Level of the microseismic background noise;
 - h. Level of the system noise;
 - i. PTA dc balance:
 - j. Oscillator alignment;

- k. Quality of the recorded WWV signal where applicable;
- 1. Time-pulse carrier;
- m. Binary coded digital time marks.

2.6 SMALL BUSINESS ADMINISTRATION VISIT

Mr. C. P. Fink of the Phoenix office of the Los Angeles Defense Contract Administration Services Region (DCASR) and Mr. H. Clinkert, Small Business Administration from Phoenix visited TFSO on 19 January in compliance with the regulations of the Small Business Administration.

2.7 SECURITY INSPECTION

Mr. K. G. Ozbolt, Industrial Security Inspector from Phoenix, Arizona, made a routine security inspection of the observatory on 18 January 1968. All security procedures were found to be in order.

2.8 EMERGENCY POWER GENERATOR

The emergency power generator was operated only 25 hours during the reporting period. Approximately 66 percent of the emergency power operation was required because of activity that resulted in commercial power fluctuations and outages.

3. EVALUATE DATA AND DETERMINE OPTIMUM OPERATIONAL CHARACTERISTICS

3.1 SHORT-PERIOD ARRAY SYSTEMS MODIFICATIONS

Most of January and February were spent replacing cable and making repairs to the 30-kilometer short-period array. All systems were considered operational by 26 February.

Tests were conducted during March to determine a method of eliminating the noise and spiking which occurred on the seismograms when the line leakage resistance became low, due to moisture. Known bad cables, grounded test lines, cables submerged in water, and water-soaked hocks were installed in some of the systems to simulate line leakages which would cause noise and spiking.

From these tests it was found that a ground loop existed between the point of the line leakage and the negative side of the power supply. The negative side of the power supply was grounded and was causing some of the spiking. The ground loop was eliminated by removing the negative side of the power supply from ground and installing a 10.0 µF capacitor between the negative side of the power supply and ground. Removing the ground loop did not eliminate all of the spiking. Also, line leakage produced changes of as much as 30 Vdc at the vault between either side of the line and ground while the 24 Vdc measured across the line at the vault appeared to be constant. This change in voltage was causing spiking because of an unbalanced circuit condition in the vault isolation filter. To balance the circuit, a 1.0 µF capacitor was installed in the vault isolation filter between the positive side of the power line and ground. (See figure 3.)

These modifications eliminated the spiking of the systems tested, but final evaluation of the modifications cannot be made until several severe storms have been experienced in the area. Systems Z1 through Z10, Z12, and Z25 have been modified, and no instances of noise or outages have been observed on these systems due to excessive moisture. As time permits, we are installing these modifications in all of the other short-period array circuits except Z33, Z34, Z35, and Z37, which will be left unmodified for use as standards for comparison, and Z36, which will be operated from battery power.

3.2 MAINTAIN TFSO FACILITIES


Severe low temperatures at Payson this winter caused several breaks in one of the building air conditioner coils. These coils are normally protected by a thermostat which shuts off outside air when the temperature drops to below 50 degrees Fahrenheit. However, water collects in the low portions of the coils; and if unusually cold weather prevails, the water will freeze and the coils may break.

The coils were repaired and replaced. In addition, the station will add an automatic drain valve to the system which will drain automatically as the thermostat shuts off the flow of outside air.

4. ANALYZE DATA

4.1 DAILY REPORTS TO THE COAST AND GEODETIC SURVEY

TFSO reports the arrival time, period, and peak amplitude of events recorded at TFSO to the Director of the Environmental Science Services Administration's



Block diagram of the power system for the short-period seismographs showing modifications made to system to reduce noise and spiking due to line leakage Figure 3.

Coast and Geodetic Survey in Washington, D. C., daily. The number of events reported by TFSO during each month of the reporting period is shown in table 2, by type.

Table 2. Events reported to the C&GS by TFSO during January, February, and March 1968

Month	Local	Near regional	Regional	Teleseisms	Total
January	6	97	17	1016	1136
February	4	88	24	835	951
March	8	76	11	885	98 0

The number of events reported by C&GS in their "Earthquake Data Report" for September, October, and November 1967, are given in table 3. Also shown in table 3, by month, are the percentages of the C&GS hypocenters in which TFSO data were used to establish the location; the percentages of the C&GS hypocenters from which TFSO recorded a P or PKP arrival, based on associated data; and the percentages of the C&GS hypocenters from which TFSO recorded a P, PKP, or later phase, based on updated ABP associated data. Figures 4 and 5 show the world-wide distribution of the C&GS-located epicenters for August, September, and October 1967. The three types of symbols used to show the epicentral locations represent the detection, by TFSO, of a P or PKP phase; the detection of an event in which the first recorded arrival was not P or PKP; and no detection by TFSO.

4.2 DAILY ANALYSIS FOR MULTISTATION EARTHQUAKE BULLETIN

Data from TFSO are combined with data from CPSO, BMSO, UBSO, and WMSO and published in a monthly multistation earthquake bulletin. The bulletins for September and October 1967, were published during this reporting period, and the ABP output for November was being published at the end of the quarter.

4.3 ROUTINE NOISE SURVEY

Measurements of ambient noise in the 0.4- to 1.4-second period range are made from the short-period 16-millimeter film seismograms, daily, at TFSO. Data are processed in Garland, and monthly cumulative probability curves of trace amplitude and ground displacement as recorded on the Z60,

Percentage of hypocenters reported in the C&GS "Earthquake Data Report" for which TFSO data were used Table 3.

No. events reported by No. C&GS TFSO hypocenters	1166 411	1059 388	1152 390	
Percent of C&GS hypocenters for which the C&GS listed a TFSO Por PKP arrival	53.4	57.2	62.1	
Percent of C&GS hypocenters for which TFSO recorded a P or PKP phase, based on associated data	6.09	68.3	71.7	
Percent of C&GS hypocenters for which TFSO recorded a P, PKP, or later phase based on updated associated data	6.69	74.0	75.8	




Figure 4. Distribution of Coast and Geodetic Survey located epicenters in the northern hemisphere for August, September, and October 1967.




Figure 5. Distribution of Coast and Geodetic Survey located epicenters in the southern hemisphere for August, September, and October 1967.

 ΣT , and ΣTF seismograms are published. Curves for the months of December and January 1968, were sent to the Project Officer during this reporting period.

5. PROVIDE OBSERVATORY FACILITIES AND ASSISTANCE TO OTHER ORGANIZATIONS

5.1 ASTRODATA DATA ACQUISITION SYSTEM

Final modifications and check-out of the Astrodata system were completed in mid-January. Recording of digital data on a 24-hour basis was started about 15 February and has continued through the rest of the reporting period except for 5 days in March. On 10 March, the input amplifier to the analog-to-digital converter failed. This problem was resolved and repaired on 15 March.

Both tape transport vacuum motors were replaced, and new recording and playback heads were installed during this reporting period. Station personnel are presently considering the possibility of building an automatic "overload" reset circuit, which would improve the reliability of the data and reduce the effort required for monitoring the Astrodata system operation by the station operators.

5.2 TELEMETRY TO MASSACHUSETTS INSTITUTE OF TECHNOLOGY

Telemetry of seven seismograph channels to Lincoln Laboratory, Massachusetts Institute of Technology (MIT), continued throughout this reporting period. MIT is notified, in advance when possible, if the seismographs are to be attenuated for special tests.

5.3 ASTROGEOLOGICAL DEPARTMENT OF THE U.S. GEOLOGICAL SURVEY

TFSO has continued to support Dr. Harold Krivoy of the Astrogeological Department of the United States Geological Survey (USGS) in Flagstaff, Arizona. Dr. Krivoy receives copies of the daily station message and all TFSO Helicorder records, not needed by the observatory, on a regular basis.

5.4 VISITORS

5.4.1 Visits by School Groups

Arizona State University students and instructors visited TFSO on 22 March. Approximately 75 visitors were given tours of the observatory and brief lectures on seismology.

5.4.2 Teledyne Visitors

Mr. Arnold Sisson, program engineer, visited the station from 4 through 19 January and from 14 through 21 March for the purpose of testing short-period array cable and to aid in long-period array setup.

Mr. Joe Herrage, C. Perry, A. Krowezyk, K. King, and G. Rude, visited the station from 31 January through 23 February for the purpose of assisting in short-period array repair.

5.4.3 Visits by Project Managers

Captain F. D. Munzlinger, AFTAC Project Officer, and Mr. B. B. Leichliter, Geotech Program Manager, were visitors at TFSO from 29 January through 1 February 1968.

Mr. J. M. Whalen, Geotech Geosciences Division Manager, was a visitor at TFSO on 11 January 1968.

5.4.4 Texas Instruments Visit

Mr. A. Fox, Texas Instruments engineer, was at the station from 20 through 26 March to install, activate, and check the multichannel filter processor (MCF).

6. RESEARCH PROGRAMS

6.1 DESIGN AND INSTALL A LONG-PERIOD ARRAY

6.1.1 Land Permitting

The United States Corps of Engineers received a new amendment to the Memorandum of Agreement from the United States Forest Service about 1 March. A copy of this amendment and approval has not been received at TFSO.

6.1.2 Array Installation

At the end of this reporting period, sites LP1, LP2, LP3, LP6, and LP7 were operational with data being recorded from the seismographs at each site. Site LP4 was completed and fully instrumented; however, because of a delay in delivery of equipment to Mountain States Telephone Company, the site will not become fully operational until about 10 April.

A camp was established at the LP5 site, and construction was started on 25 March. Vault installation was completed by 29 March; we plan to install the instruments by 3 April. The generator and microwave installation for LP5 is scheduled to be completed by 5 April. Our application for a microwave license is still pending with the Federal Communications Commission. Some problems developed in the 2-wire circuit furnished to the telephone company. The circuits are routed through a 4-wire termination set at each end; however, some cross-talk problems exist. A filter was designed, and its effectiveness in reducing the cross-talk was evaluated. The effectiveness of this filter was limited; however, based on the results of the tests, other filter networks are being designed for these two circuits.

Data from all sites except LP1 are approximately 6 dB noisier than normal due to the fact that final vault covering has not yet been completed, and the instruments have not fully stabilized. This work, along with final site cleanup, is scheduled to be started about 15 April.

6.1.3 Long-Period Site Survey

Preliminary survey data have been received for all long-period sites. The sites were surveyed to a wooden "marker" stake because the vaults had not been constructed at the time of the survey. The offset between the stake and center vault has been surveyed at each site; the corrections should be applied to the final coordinates when they are received from the 1381st Geodetic Survey Squadron.

6.2 EVALUATION OF A HIGH-FREQUENCY SEISMOGRAPH

The high-frequency seismograph was received at TFSO during this reporting period; however, we have not yet installed it for testing. Installation is planned for April.

6.3 MULTICHANNEL FILTER PROCESSOR

The MCF was received at TFSO in early February, and we established input-output lines; however, we could not activate the processor until mid-March when a modified power supply was received from the power supply


manufacturer. By the end of March the MCF was operating, and a program received from the Project Officer had been implemented. Two changes were made to the power circuits: A larger power input plug was installed to alleviate a serious heating and shorting problem at the radio interference filter input; and the cooling blower units were removed from the main power line circuit and re-routed directly to an external power source.

The auxiliary processor rack was checked and found to be operating properly. The auxiliary processor is presently not connected to the MCF so that the power load could be dropped. The TI representative conducted a short course in programming, machine processes, and troubleshooting for three TFSO personnel.

Ten beam-formed outputs are presently being recorded on 16-millimeter film. The magnification of these seismographs at their steered azimuth and velocities is about 7000K at 1 cps. The reference timing is delayed with reference to Z1. All short-period channels except six (Z3, Z5, Z7, Z8, Z12, and Z16) are used in forming the beams. The beams presently being recorded, are given in table 4, and examples of the response of the beam-formed outputs to teleseismic signals are shown in figures 6, 7, and 8.

Table 4. Beams being formed by the multichannel filter using TFSO short-period array seismographs

Steered Azimuth (degrees)	Steered Horizontal Velocity (kilometers/ second)	Distance (degrees)
353.8	25	97
317.1	18	70
318.6	16	60
311.1	15	51
329.1	13	36
4.2	19	72
248.5	22	85
129.7	12	27
137.5	18	67
29.1	16	61
	Azimuth (degrees) 353.8 317.1 318.6 311.1 329.1 4.2 248.5 129.7 137.5	Azimuth (degrees) Velocity (kilometers/second) 353.8 25 317.1 18 318.6 16 311.1 15 329.1 13 4.2 19 248.5 22 129.7 12 137.5 18



TFSO short-period seismogram showing the beam-formed MCF outputs responding to a teleseismic Parrival from the southeast - epicenter unknown. (X10 enlargement of 16-millimeter film) Figure 6.


TFSO 29 Mar 1968 RPN 089

DG 7264



TFSO short-period seismogram showing the beam-formed MCF outputs responding to a teleseismic Parrival from the northwest - epicenter unknown. (X10 enlargement of 16-millimeter film) Figure 7.

29 Mar 1968 RPN 089 DG 7264



responding to a teleseismic P arrival from the west-southwest - epicenter TFSO short-period seismogram showing the beam-formed MCF outputs unknown. (X10 enlargement of 16-millimeter film) Figure 8.

TFSO 30 Mar 1968 RPN 090

APPENDIX TO TECHNICAL REPORT NO. 68-17 STATEMENT OF WORK TO BE DONE

STATEMENT OF WORK TO BE DONE (AFTAC Project Authorization No. VELA T/8702/S/ASD) (32)

Taska:

a. Operation:

- (1) Continue operation of the Tonto Forest 5 'smological Observatory (TFSO), normally recording data continuous
- (2) Evaluate the saismic data to determine optimerational characteristics and make changes in the operating parameters may be required to provide the most effective observatory possible. Addition and modification of instrument are within the scope of work. However, such instrument modifications and additions, data evaluation, and major parameter changes are subject to the prior approval of the AFTAC project officer.
- (3) Conduct routine daily analysis of seismic data at the observatory and transmit daily seismic teletype reports to the Coast and Geodetic Survey, Environmental Science Services Administration. Washington Science Center, Rockville, Maryland, using the established report format and detailed instructions.
- (4) Record the results of daily analysis on magnetic tape in a format compatible with the automated bulletin program used by the Seismic Data Laboratory (SDL) in their preparation of the seismological bulletin of the VELA-UNIFORM seismological observatories. The format should be established by coordination with SDL through the AFTAC project officer. The schedule of routine shipments of these prepared magnetic tapes to SDL will be established by the AFTAC project officer.
- (5) Establish quality control procedures and conduct quality control, as necessary, to assure the recording of high quality data on both magnetic tape and film. Past experience indicates that a quality control review of one magnetic tape per magnetic tape recorder at the observatory during each week is satisfactory unless quality control tolerances have been exceeded and the necessity of additional quality control arises. Quality control of magnetic tape should include, but need not necessarily be limited to, the following items:
 - (a) Completeness and accuracy of operation logs.
- (b) Accuracy of observatory measurements of system noise and equivalent ground motion.
 - (c) Quality and completeness of voice comments.
- (d) Examination of all calibrations to assure that clipping does not occur.

REPRODUCTION

- (e) Determination of relative phase shift on all array seismographs.
 - (f) Measurement of DC unbalance.
 - (g) Presence and accuracy of tape calibration and alignment.
 - (h) Check of uncompensated noise on each channel.
 - (i) Check of uncompensated signal-to-noise of channel 7.
- (j) Check of general strength and quality of timing data. derived from National Bureau of Standards Station WWV.
- (k) Check of time pulse modulated 50 cps on channel 14 for adequate signal level and for presence of time pulses.
- (1) Check of synchronization of digital time encoder with wwv.
- (6) Provide observatory facilities, accompanying technical assistance by observatory personnel, and seismological data to requesting organizations and individuals after approval by the AFTAC project officer.
- (7) Maintain, repair, protect, and preserve the facilities of TFSO in good physical condition in accordance with sound industrial practice.
- b. Instrument Evaluation: On approval by the AFTAC project officer, evaluate the performance characteristics of experimental or off-the-shelf equipment offering potential improvement in the performance of observatory seismograph systems. Operation and test of such instrumentation under field conditions should normally be preceded by laboratory test and evaluation.

c. Special Investigations:

- (1) Conduct research investigations as approved or requested by the AFTAC project officer to obtain fundamental information which will lead to improvements in the detection capability of TFSO. These programs should take advantage of geological, meteorological, and seismological conditions of the observatory. The following special studies should be accomplished:
- (a) Evaluate the beam-steering capabilities of the 30-kilometer long- and short-period vertical seismometer arrays.
- (b) Determine the detection capabilities of the 30-kilometer long- and short-period vertical seismometer arrays.



- (c) Study the properties of the noise field with the new arrays.
- d) Determine the reliability of instrumentation in the new arrays.
- (2) Research might pursue investigations in, but is not necessarily limited to, the following areas of interest: microseismic noise, signal characteristics, data presentation, detection threshold, and array design (surface and shallow borehole).
- (3) Prior to commencing any research investigation, AFTAC approval of the proposed investigation and of a comprehensive program outline of the intended research must be obtained.

Unclassified						
. Security Classification						
DOCUMENT CONT	ROL DATA - R	& D				
(Security classification of title, hody of abstract and indexing	annotation must be	entered when the	overall report is classified)			
Geotech, A Teledyne Company		20. REPORT SI	ECURITY CLASSIFICATION			
3401 Shiloh Road		Unclassified				
		2b. GROUP				
Garland, Texas						
Operation of the Tonto Forest Seismologi	cal Observa	tory				
Quarterly Report No. 1, Project VT/870	2, l January	through 3	31 March 1968			
4. OESCRIPTIVE NOTES (Type of report and inclusive dates)						
8. AUTHOR(S) (First name, middle initial, last name)		·				
a						
Geotech Staff						
6. REPORT OATE						
	74. TOTAL NO. OI	PAGES	7b. NO OF REFS			
15 April 1968	33					
AF 33657-68-C-0766	94. ORIGINATOR'S	REPORT NUME	BER(\$)			
b. PROJECT NO.		TR 68-17	,			
VELA T/8702		1R 08-1	1			
c.	95. OTHER REPORT NO(5) (Any other numbers that may be assigned					
ARPA Order No. 624	this report)	(1217)	The manuals that may be essigned			
d. ARPA Program Code No. 6F10						
10. DISTRIBUTION STATEMENT						
This document is subject to special expo	rt controls a	ind each t	ransmittal to a			
foreign national may be made only with p	rior approv	al of the C	Thief of AFTAC			
11. SUPPLEMENTARY NOTES	_					
The control of the co	12. SPONSORING M		Projects Agency			
			ction Office			
		on, D. C.	ction Office			
13. ABSTRACT	Washingt	on, D. C.				
I The is which						
I have a report of the work accomplished	d on Project	VT/8702	from 1 Jaruary			
through 31 March 1968. Project VT/870;	2 includes th	e operatio	on evaluation			
and improvement of the Tonto Forest Seis	smological (bservator	TESO) located			
near Payson, Arizona. It also includes s	pecial resea	irch and t	est functions			
carried out at TFSO and research and dev	velopment ta	sks perfo	rmed by the			
Garland, Texas, staff using TFSO data. /)	•				
A						
/	`					

Unclassified
Security Classification

KEY WORDS	LIN	KA	LIN	IK B	LINK C		
	ROLE	WT	ROLE	WT	ROLE	w	
						<u> </u>	
Long-period array			ļ				
On-line beamforming		[ļ	1			
37-element short-period array	1	ŀ	ĺ				
Seismograph operating parameters				1	'		
operating parameters		1	1	ļ	!		
					į i		
			ĺ	ł			
				İ	1		
	1			Ĭ	1 1		
					, ,		
	1				1		
		l j					
	1 1	1					
		1					
		l			1		
		ł	- 1				
	1 1	j		I			
			- 1	i			
				1			
		j	1	- 1			
		1	l		i		
					- 1		
			- 1	1			
		1		- 1			
				1			
İ							
1							
			- 1		1		
			1				
		1		j	l		
j		1	Ţ	1	1		
			1				
	1						
]		ļ			
}	1			1			
j			ŀ	1	- 1		
1			ľ				
t				1			
}				ł			
1	- 1						
1							
	l						
· I	- 1				i		
II.							
			ļ				

Unclassified Security Classification